


CHIN (RIGHT)



CHIN (LEFT)

Note: Due to a glitch in manufacturing, some of the left chin boards do not have a silkscreen. This does not affect the board; you just have to make sure you pay attention when placing these components. The picture below shows a board with components already in place for your reference.

